0015



State of Utah

DIVISION OF OIL, GAS AND MINING

gx JH

INSPECTION REPORT

Michael O. Leavitt Boy 145801

Governor Sa Ted Stewart

Executive Director James W. Carter Division Director Box 145801 Partial: XXX Complete: Exploration: Salt Lake City, Utah 84114-580 Inspection Date & Time: 7/8/97 / 12:45p.m.-4:00p.m. (801) 359-3940 (Fax) Date of Last Inspection: 6/10/97

Mine Name: Bear Canyon Mine County: Emery Permit Number: ACT/015/025						
Permittee and/or Operator's Name: Co-Op Mining Company						
Business Address: P. O. Box 1245, Huntington, Utah 84528						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Charles Reynolds						
State Officials(s): Peter Hess Federal Official(s): None						
Weather Conditions: 70's, Windy, Showers						
Existing Acreage: Permitted-1531 Disturbed-24 Regraded-0 Seeded-0 Bonded-24						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/_Temporary Cessation/_Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	\Box	[XX]	
2.	SIGNS AND MARKERS	[XX]	\Box	\Box	\Box
3.	TOPSOIL	[XX]	Ш	Ш	\Box
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	\Box	\Box	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX] [XX]	Ш	$\overline{[XX]}$	Ll
c.	OTHER SEDIMENT CONTROL MEASURES		Ш	Ш	ĹÌ
d.	WATER MONITORING	\Box	ĹĬ	ĹĬ	\Box
e.	EFFLUENT LIMITATIONS	Π	Π	ĹĬ	ĹÌ
5.	EXPLOSIVES	Π	ĹĬ	ĹĬ	Ш
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		[XX]	\Box	ĹÌ
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	\Box	XXI	ĹĬ	
8.	NONCOAL WASTE	$\overline{[XX]}$	Ц	\Box	Ш
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	\Box	[XX]	\Box	\Box
l0.	SLIDES AND OTHER DAMAGE		[XX]	Ш	\Box
11.	CONTEMPORANEOUS RECLAMATION	Π	[XX]	ĹĬ	ĹÌ
12.	BACKFILLING AND GRADING	\Box	[XX]	\Box	Ш
13.	REVEGETATION	Ī	[XX]	\Box	ĹÌ
14.	SUBSIDENCE CONTROL	Π	Ш	ĹÌ	
15.	CESSATION OF OPERATIONS		Ĺ	\Box	\Box
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	Ш	\Box	\Box
b.	DRAINAGE CONTROLS	XX	LÌ	ĹÌ	ĹĬ
١7.	OTHER TRANSPORTATION FACILITIES	ΪΧΧΊ	\Box	\Box	ĹĬ
l 8.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	Π	\Box	ĹĬ
19.	AVS CHECK (4th Quarter-April, May, June) (date)		\Box		Π
20.	AIR QUALITY PERMIT	\Box	\Box	\Box	ΙĬ
21.	BONDING & INSURANCE	īī		\Box	ΞĪ



INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 7/8/97

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

Permit amendment ACT/007/038-97B, which involves the installation of approximately 260 cubic yards of blacktop in the scalehouse area and its adjacent primary roads, has been returned to the permittee for deficiencies. Mr. Reynolds indicated that this amendment has been placed on the back burner so that the amendment addressing the new Federal lease application can be concentrated on.

4b. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

It was observed that the permittee has re-initiated the cleanout of sediment pond "A". From what was seen remaining in the FEL's bucket, the material appears to be quite soupy. A project of this type often takes several months to complete, as additional drying time is usually needed to improve the handling characteristics of the muck.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Charles Reynolds (Co-Op)

Given to: Joe Helfrigh (DOCM)

Filed to: Price Field Office

Given to: Joe Helfrich (DOGM)

Date: July 9, 1997

Filed to: Price Field Office

Jule: <u>van 2, 1227</u>

Inspector's Signature: Peter Hess

#46